

Date: Thu, 15 Sep 94 04:30:16 PDT
From: Ham-Ant Mailing List and Newsgroup <ham-ant@ucsd.edu>
Errors-To: Ham-Ant-Errors@UCSD.Edu
Reply-To: Ham-Ant@UCSD.Edu
Precedence: Bulk
Subject: Ham-Ant Digest V94 #310
To: Ham-Ant

Ham-Ant Digest Thu, 15 Sep 94 Volume 94 : Issue 310

Today's Topics:
 2m Repeater Antennas ?

Send Replies or notes for publication to: <Ham-Ant@UCSD.Edu>
Send subscription requests to: <Ham-Ant-REQUEST@UCSD.Edu>
Problems you can't solve otherwise to brian@ucsd.edu.

Archives of past issues of the Ham-Ant Digest are available
(by FTP only) from UCSD.Edu in directory "mailarchives/ham-ant".

We trust that readers are intelligent enough to realize that all text
herein consists of personal comments and does not represent the official
policies or positions of any party. Your mileage may vary. So there.

Date: 14 Sep 1994 07:38:23 -0500
From: ihnp4.ucsd.edu!agate!library.ucla.edu!europa.eng.gtefsd.com!
newsxfer.itd.umich.edu!news.cic.net!news.plexus.com!news.plexus.com!not-for-
mail@network.ucsd.edu
Subject: 2m Repeater Antennas ?
To: ham-ant@ucsd.edu

Hi. We had been using a Hygain G-7 antenna. The antenna was
generating noise on the receive side of our repeater whenever
the transmitter was above 5 watts. We swapped the G-7 with
a ringo and the noise moved. So now we are looking at obtaining
a replacement. We have some information on colinear antennas.

I was wondering what type of antennas are recommended or a list
of ones to stay away from. We want something that will last
and not give us any more problems with noise.

The repeater is on 146.655 -.600 pl 107.2

Thanks for any replys. 73 de3 kf9cs in Appleton, wi

cul Mark

Work: mark.heimermann@plexus.com
Home: 76210.1033@compuserve.com
Packet: KF9CS @KA9JAC.WI.USA.NOAM

End of Ham-Ant Digest V94 #310
